# Lateral Plungers • smooth, without seal, with female thread

22150.1041



# **Product Description**

To be used for positioning and applying pressure, e.g. during painting and sandblasting.

#### **Material**

#### Body

Aluminium Al

#### Threaded washer

· Steel, blackened

#### **Spring**

· Steel, blackened

#### **Assembly**

Formula for calculating the center distance for the mounting hole:

 $I_0 = z/2 + w + x$ 

 $I_0$  = center distance,

y = workpiece height,

w = workpiece length,

x = stroke

z = stop diameter

Calculation dimension x for workpieces:

 $x = d_2/2 - s$ 

Installation by pressing in.

## Characteristic

Version standard spring load = spring from steel, blackened

## More information

#### Notes


DH8

Individual set screws can be screwed in the plate with threaded hole.

#### **Further products**

• Eccentric Mounting Bushings, for lateral plungers, smooth

# **Drawing**



# Order information

Dimens	Dimensions				Stroke	Location		Ĭ	Art. No.			
d₁	d <sub>2</sub>	F max. <sup>1)</sup> ~	d <sub>3</sub>	I <sub>1</sub> -1	l <sub>2</sub>	l <sub>3</sub>	I <sub>4</sub>	S	hole D H8	max.	_	
[mn	n]	[N]		<u>'</u>	[mm]			[mm]	[mm]	[°C]	[g]	
Standard spring load												
16	M6	150	10.2	18	11.5	7.5	1.7	3.2	16	250	9.4	22150.1041

<sup>1)</sup> statistical average value



Halder, Inc. www.halderusa.com

Accessories								
	Dimensions d <sub>1</sub>	ĭ	Art. No.					
	[mm]	[g]						
assembly tool								
	16	105	22150.0833					

# Compliance

## **RoHS** compliant

Compliant according to Directive 2011/65/EU and Directive 2015/863.

# Does not contain SVHC substances

No SVHC substances with more than 0.1% w/w contained - SVHC list [REACH] as of 23.01.2024.

## Does not contain Proposition 65 substances

No Proposition 65 substances included.

https://www.P65Warnings.ca.gov/

## **Free from Conflict Minerals**

This product does not contain any substances designated as "conflict minerals" such as tantalum, tin, gold or tungsten from the Democratic Republic of Congo or adjacent countries.



Halder, Inc.

www.halderusa.com Page 2 of 2

Published on: 4.2.2024