# **Precision Index Plungers** • with tapered pin

22130.0125



## **Product Description**

Precision index plungers together with bushings are a perfect combination for quick positioning and mounting.

The precise tolerance of both, the precision index plunger and the bushing, guarantees a high repeatability of these two elements.

#### **Material**

#### Pin

 Case-hardened steel, case-hardened, blackened and ground

#### **Bushing**

 Case-hardened steel, case-hardened, blackened and ground

#### Body

• Case-hardened steel, case-hardened, blackened and ground

## Ball knob

· Thermoplastic, greyish black

#### **Assembly**

For precise adjustment, the grip ball and plunger should be glued grease-free after assembly. Detailed assembly instructions can be downloaded as a PDF file under "Documents".

#### **Operation**


When using locking index plungers the knob is pulled out and turned  $90^{\circ}$ .

#### More information

#### Notes

Bushings must be ordered separately.

#### **Drawing**





Halder, Inc.

www.halderusa.com

### **Order information**


Nominal	Dimensions									Spring load <sup>1)</sup>		I	Art. No.	
diameter	d₁	d <sub>2</sub>	d <sub>3</sub>	d <sub>4</sub>	d₅	I <sub>1</sub>	l <sub>2</sub>	l <sub>3</sub>	I <sub>4</sub>	I <sub>5</sub>	F <sub>1</sub>	F <sub>2</sub>		
			n6			min.					~	~		
	[mm]													
[mm]					[mm]						l	[N]	[g]	
[mm]	ing – pict	ure 1			[mm]						I	[N]	[9]	

<sup>1)</sup> statistical average value

## **Accessories**

	Nominal diameter		I	Art. No.						
		d₁	d <sub>2</sub>	d <sub>3</sub>	I <sub>1</sub>	l <sub>2</sub>				
		+0.1		n6	min.					
	[mm]		[9]							
Socket for precision index plungers, tapered – picture 3										
	25	19.70	42	38	19	16.0	114	22130.0196		

## **Application example**



## Compliance

## **RoHS** compliant

Contains lead - compliant according to exceptions 6a / 6b / 6c.

## Contains SVHC substances >0,1% w/w

Contains lead - SVHC list [REACH] as of 23.01.2024.

## **Contains Proposition 65 substances**



Lead can cause cancer and reproductive harm from exposure https://www.P65Warnings.ca.gov/

## **Free from Conflict Minerals**

This product does not contain any substances designated as "conflict minerals" such as tantalum, tin, gold or tungsten from the Democratic Republic of Congo or adjacent countries.



Halder, Inc. www.halderusa.com